

Garth Road Site (TXD981517691)
9/26/88

Recommendation: No further remedial action planned under Superfund; action may be appropriate under RCRA - Subtitle D.

Discussion:

The Garth Road Site is 5.3 acre lot which was identified during the French Ltd. site investigation as a possible dumpground for petrochemical wastes. However, during a recent onsite inspection by Ecology and Environment, Inc, no evidence of any hazardous substance disposal could be substantiated. No odors, soil stains, or stressed vegetation were identified. In fact, the site was heavily overgrown by brush. However, piles of waste lumber, tires, and other household scrap were found. Although this material meets the regulatory definition for solid waste, it is not considered to be hazardous. For this reason, no further remedial action is planned under Superfund authority. However, this site will be referred to the state programs section of RCRA to evaluate whether any of the RCRA - Subtitle D regulations have been violated.

bcc: Bryan Burgess (6H-HS)

D.G.
9/26/88